





	🖧 (230 VAC) 3000 W
T = (0.520) min	
	(–10…+60)°C
	30 (≤1 mA)




(finder)











2











### ENGLISH

#### 14.01 MULTIFUNCTION ELECTRONIC STAIRCASE TIMER

Terminals N and 3 are duplicated so wiring can connect to the top, or the bottom (dotted lines) of the unit. Ensure the N for the lighting load is taken directly from the supply system N, and not through the unit. I.E. do not use the "duplicated" N to provide the N for the lighting load. 1a 3 wire connection diagram-with push bottom link to the NEUTRAL (N) **1b** 4 wire connection diagram - with push bottom link to the LINE (L)

## 2 FRONT VIEW

- A = Function rotary selector
- **B** = Time adjustment trimmer
- C = LED

# **3** FUNCTIONS

- **BE** = Staircase relay
- **BP** = Staircase relay with early warning
- **IT** = Timing step relay
- **IP** = Timing step relay with early warning
- **RI** = Step relay
- 👶 = Light ON
- ME = Staircase relay + Staircase maintenance

In addition to the Staircase relay function (BE), an impulse of ≥5 seconds will close the output contact for 60 minutes, after which time the contact will open. Ideal for maintenance or cleaning activities. The 60 minute timing can be interrupted by a further impulse of  $\geq 5$  seconds, and the output contact then opens

**MP** = Staircase relay with early warning + Staircase maintenance In addition to the Staircase relay function (BP), an impulse of ≥5 seconds will close the output contact for 60 minutes, after which time the contact will open. Ideal for maintenance or cleaning activities. The 60 minute timing can be interrupted by a further impulse of  $\geq$ 5 seconds, and the output contact then opens

#### NOTE

"Zero Crossing" load switching. The output blinking within the Early Warning functions (BP and IP) could cause re-start problems for fluorescent lamps with electromagnetic chokes (both conventional and compact types).

We consequently suggest not to use such lamps with these functions.

