






14.01-P









































ENGLISH

14.01 PUSH-IN MULTIFUNCTION ELECTRONIC STAIRCASE TIMER

FRONT VIEW

- A Function rotary selector
- B Time adjustment trimmer
- C LED
- TERMINAL PUSH-IN CONNECTION
- 2a Connection
- 2b Disconnection
- Terminals N and 3 are duplicated so wiring can connect to the top, or the bottom (dotted lines) of the unit. Ensure the N for the lighting load is taken directly from the supply system N, and not through the unit. I.E. do not use the "duplicated" N to provide the N for the lighting load.
 - 3a 3 wire connection diagram-with push bottom link to the NEUTRAL (N)
- 3b 4 wire connection diagram with push bottom link to the LINE (L)

4 FUNCTIONS

- **BE** Staircase relay
- **BP** Staircase relay with early warning
- Timing step relay
- Timing step relay with early warning
- Step relay
- Light ON
- ME Staircase relay + Staircase maintenance
- In addition to the Staircase relay function (BE), an impulse of ≥5 seconds will close the output contact for 60 minutes, after which time the contact will open. Ideal for maintenance or cleaning activities. The 60 minute timing can be interrupted by a further impulse of ≥5 seconds, and the output contact hen opens
- MP Staircase relay with early warning + Staircase maintenance In addition to the Staircase relay function (BP), an impulse of ≥5 seconds will close the output contact for 60 minutes, after which time the contact will open. Ideal for maintenance or cleaning activities. The 60 minute timing can be interrupted by a further impulse of ≥5 seconds, and the output contact then opens

"Zero Crossing" load switching. The output blinking within the Early Warning functions (BP and IP) could cause re-start problems for fluorescent lamps with electromagnetic chokes (both conventional and compact types).

We consequently suggest not to use such lamps with these functions.

